

# Great Alne Flood Action Group

The Story So Far....

17<sup>th</sup> October 2025

### Great Alne - A rural village somewhere in South Warwickshire


c390 Properties c600 Residents

Incorporates Great Alne Park Retirement Village (154, 341 when full)

Crossroads between Studley,
Stratford upon Avon, Alcester, and
Wootton Wawen



## A Unique Topography



Parish covers 1764 acres

In the Middle of Rolling Hills

Surrounded by Agriculture

And in the Valley of the River Alne

Huge River Catchment Area


### 2023 GAPC - Community Survey

Key Issue - Vehicular Access - Flooding the Cause


Great Alne Parish Council commissioned Flood Action Group (FLAG)


"The Primary FLAG goal was to ensure access to the village in times of heavy rain, which would improve:


- School attendance levels,
- health workers and carers service delivery to the over sixties and extremely vulnerable,
- commuting to and from work,
- delivery of goods and services into the village,
- Public transport services,
- emergency service capabilities and
- profitability of village businesses"



## Great Alne Parish FLAG Approach







#### Great Alne Parish FLAG - Structure

Structured Delivery Plan Understand the Problem

**Identify Root Causes and Flood Assets** 

Recruit and Train FLAG Volunteers and Identify Key Stakeholders

Develop Delivery Plan

Secure SDC CCC Funding (1st Release)

Benchmark Existing Performance

Manage Plan Delivery

Measure Physical Improvements

Report Activity, Results and Action Plans

Lessons Learned



### Great Alne Parish FLAG – Engagement

Secure and
Maintain
Stakeholder
Commitment

Identify All Key Stakeholders and secure ongoing commitment


Agree Stakeholder Roles, Responsibilities and Deliverables


Manage Stakeholder Delivery across Plan Timeline

Constant Communication was the key to successful delivery of activities



## Great Alne Parish FLAG – Learning





Understanding your local water system can be complicated and takes time

You can't do this on your own

Stakeholder Commitment is Critical


Constant Communication is Key

Become a Pain with Statutory Bodies

Formally Report Findings to WCC (or your Statutory Body) to ensure they are fully aware of the works necessary to improve the situation

<u>link</u>

None of this is Easy – but it can be done



### Drain Status Over Time 2024/5

FLAG Team Created Monthly RAG Status Commenced & CPW Cleared Monthly Drain Maintenance Commenced

Little Alne Drain Repairs Completed

Spernal Lane Ditch Excavated

WWT NFM Work Commenced

Stoat Lane Ditch Excavated

Sub-Scan Drain Clearing & CCTV
Inspection Started – Completed in November
Parish Ditch, Sump and Alne Cote Field
Ditches Excavated

Detailed Drain Condition Report Issued to WCC

WCC Commenced works

	Green	Amber	Red	Total	Rating
March	55	0	59	114	-4%
April	59	0	55	114	4%
May	70	0	44	114	23%
July	73	0	41	114	28%
August A	82	0	33	115	43%
August B	96	0	19	115	67%
September	91	13	12	116	68%
October	110	4	2	116	93%
November	113	1	2	116	96%
December	110	4	2	116	93%
January	90	16	10	116	69%
February	91	16	9	116	71%
March	110	5	1	116	94%
September	115	2	0	117	98%

## Pictures

















